

SPACE EXTENSION QUBE240



Please scan to watch the video
„TrinityF90+_Space extension Lidar Qube240“

Link: https://youtu.be/5sFGSBXk_eU

1. REQUIRED PARTS

Nr.	4260574663261 · Trinity F90+ Foam Rework for Lidar Kit	Quantity	Included
1	Lidar Foam Cutting Jig	1	✓
2	Scalpel Handle Nr. 4	1	✓
3	Scalpel Figure 18	1	✓


INSTRUCTION STEP BY STEP:

Removing the dome cover


1. Detach the black cover carefully with the scalpel.



2. Place the jig in the middle and mark the edges with a permanent marker.
Please make sure the edge of the jig aligns with the foam.



3. Cut out the marked area with the scalpel. Do not damage the cables and don't cut deeper than 1 cm.



4. The Black cover is not needed anymore.

